

## Diagnostická zpráva vozidel

Zpráva je vytvořen **LAUNCH X-431**

## Informace o vozidle



Rok:2020

Značka:Kia

Model:Niro (DE EV)

VIN:KNACC81GFL5055876

Engine Size:100KW/150KW

vzdálenost v mílích:89661 km

Verze softwaru vozidla:V46.50

Diagnostické Verze aplikace:V8.00.031

Diagnostická cesta:Automatically Search &gt; General Area &gt; Niro (DE EV) &gt; 2020 &gt; 100KW/150KW

## Repair Shop

Dílna:VOZIMAUTA s.r.o.

Adresa:

Zip Code:

Telefon:

e-mail:

SN:989347747304

Zkušební doba:2026-02-06 12:27:24



## System fault code Pre-Repair

Následující systémy jsou v pořádku:

- 1.ABS/ESP(+EPB)
- 2.Forward Collision-Avoidance Assist (FCA/SCC)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.Full auto Air Temperature Control
- 6.CLU(Cluster Module) (4inch)
- 7.CLU(Cluster Module) (7inch)
- 8.WPC (Wireless Power Charger)
- 9.Integrated Body Control Unit-BCM
- 10.Integrated Body Control Unit-TPMS
- 11.MLM (Mood Lamp Module)
- 12.MDPS (Motor Driven Power Steering)



- 13.Smart Key Unit
- 14.MFC (Multi Function Camera) Ⓞ ADAS
- 15.Blind-Spot Collision Warning-Left Ⓞ ADAS
- 16.Blind-Spot Collision Warning-Right Ⓞ ADAS
- 17.RVM (Rear View Monitor) Ⓞ ADAS
- 18.EV Motor Control System
- 19.HEV Battery System
- 20.Virtual Engine Sound System
- 21.VCULDC
- 22.AAF (Active Air Flap)
- 23.Amplifier
- 24.E-Shifter
- 25.IGPM (Integrated Gateway Power Control Module)
- 26.OBC (On Board Charger)
- 27.CCM (Charging Control Module)

.....

**Prohlášení o odmítnutí záruk**

This test report is for reference only for vehicle test and maintenance. The vehicle operating data provided in this report are all static data. The detailed dynamic diagnostic data can be read by professional maintenance device, and LAUNCH will not be liable for any accidents and failures arising therefrom!